

Technical Note

Title: TranXit on 400 conflicting with Sound IRQ

Date: 09/11/95

Product Fields: 400 / Satellite Pro
Software - Preinstalled

Toshiba America Information Systems, Inc. has done its best to ensure the accuracy of this information. Toshiba America Information Systems, Inc. reserves the right to revise or make obsolete some or all of the contents without obligation to notify any person of such revisions or changes. Despite every effort to the contrary, errors, omissions or discrepancies may have occurred in preparation of this document and Toshiba America Information Systems, Inc. assumes no liability for damages incurred due in part or in whole to such errors.

PROBLEM

Cannot setup TranXit software on the 400CDT.

SOLUTION

This can be caused by the interrupt setting for the sound card. If the sound card is set for interrupt 7, then conflict will exist with the parallel port (LPT1).

From TSETUP, change the sound interrupt to another setting other than 7.

It has been reported that some of the out of box units have the sound interrupt set to interrupt 7.

Keywords

TRANXIT 400 INFRARED PORT